

[May 29, 2022 Reliable NACE-CIP2-001 Exam Tips Test Pdf Exam Material [Q34-Q51]



[May 29, 2022] Reliable NACE-CIP2-001 Exam Tips Test Pdf Exam Material
New 2022 NACE-CIP2-001 Test Tutorial (Updated 100 Questions)

NEW QUESTION 34

The best choice of instrument for holiday testing of thick film concrete coatings is:

- * Low Voltage Sponge Type
- * High Voltage DC Pulse Type
- * High Voltage DC Constant Current
- * High Voltage AC

NEW QUESTION 35

Surface preparation methods for Non-ferrous metals are:

- * The same as for Ferrous metals
- * The same for all Non-Ferrous metals
- * Specific for each type of Non-ferrous metal

- * Not required

NEW QUESTION 36

When environmental enclosures are being used an inspector needs to be concerned about:

- * Lighting
- * Air changes
- * Structural integrity
- * a), b), and c)

NEW QUESTION 37

The standards defining surface cleanliness achieved by centrifugal blast cleaning are:

- * Different than air blast cleaning
- * The same as air blast cleaning
- * Slightly different to air blast cleaning
- * Comparable to air blast cleaning

NEW QUESTION 38

It is always possible to see moisture on a steel substrate:

- * True
- * False

NEW QUESTION 39

WJ-1 is always performed using UHWJ at pressures above 210 MPa (30,000 PSI)

- * True
- * False

NEW QUESTION 40

An Inspection and Test Plan is required when:

- * It is always required
- * When the Coating Applicator requests one
- * When the Owner specifies one
- * When the Inspector requests one

NEW QUESTION 41

You are a NACE Level 2 Coating Inspector who has just arrived on a job in progress where there is no Inspection and Test Plan (ITP). The first morning you arrive the job is behind schedule and you are asked to take DIY Film Thickness readings.

Your FIRST preferred course of action is to:

- * Refuse to take readings until an is in place
- * Develop your own methodology and proceed take the readings
- * Use a generally accepted industry standard and to take readings
- * Call your supervisor

NEW QUESTION 42

You should bulk store coatings containing isocyanates

- * in a well ventilated area separate from the work place.
- * in a heated warehouse.
- * in a refrigerated warehouses
- * wherever it is convenient

NEW QUESTION 43

When NACE/SSPC WJ 1 is referenced; what type of equipment would the Inspector expect to see on the job:

- * Power Tools
- * Abrasive Blasting Equipment
- * Water Jetting Equipment
- * Scarifiers

NEW QUESTION 44

In powder coatings, when the particles of powder begin to flow but are not fully liquid, they are in what stage?

- * Flow stage
- * Wetting stage
- * Cure stage
- * Gel stage

NEW QUESTION 45

The number of air turns in an enclosure can be affected by all of these EXCEPT

- * time of the year (winter/summer).
- * type of dehumidification equipment (refrigerant or desiccant).
- * manufacturer of the equipment.
- * coating type.

NEW QUESTION 46

You can use magnifiers to examine all of the following EXCEPT

- * Surface profile
- * Surface cleanliness
- * Blisters
- * Mill scale

NEW QUESTION 47

You are the NACE Coating Inspector on a tank lining project and are asked to perform a high voltage holiday test after the coating applicators have completed their final repairs. After meeting all the confined space entry permit you enter the tank and notice a very strong odor of solvent.

Your first course of action should to:

- * Investigate to find the source of the odor
- * Don your air supplied respirator and continue the testing
- * Exit the tank and immediately and report the problem to the nearest safety supervisor
- * Exit the tank and document the incident in your daily report

NEW QUESTION 48

Antifouling coatings are regulated by international treaties.

- * True
- * False

NEW QUESTION 49

NACE No.13/ SSPC 6 identifies the use of:

- * Abrasive blasting only
- * Waterjetting only
- * Steam cleaning only
- * Various methods of cleaning

NEW QUESTION 50

Measuring methyl ethyl ketone (MEK) resistance of ethyl silicate inorganic zinc-rich primers by solvent rub requires

- * 25 single rubs with a saturated cloth.
- * 35 single rubs with a saturated cloth.
- * 50 double rubs with a saturated cloth.
- * 25 double rubs with a saturated cloth.

NEW QUESTION 51

You are the NACE Level 2 inspector reviewing the documentation from a NACE Level 1 you notice significant documentation errors.

Your FIRST preferred course of action is to:

- * Correct the errors yourself and suggest the Level 1 inspector be replaced
- * Correct the errors yourself and advise your supervisor that the Level 1 Inspector is incompetent
- * Have the Level 1 Inspector correct the errors and set up remedial training to improve the quality of documentation
- * Correct the errors yourself and submit the reports without any further action

NACE-CIP2-001 Cert Guide PDF 100% Cover Real Exam Questions:

<https://www.actualtests4sure.com/NACE-CIP2-001-test-questions.html>